

GVSU Housing Fire Safety Systems (2011)

Living Centers	Alarms Monitored at CUB	Sprinkler System	Smoke Detector	Fire Extinguisher	Evacuation Placards	Number of Annual Fire Drills
Copeland	X	No	X	X	X	1
Calder Residence	X	No	X	X	X	1
Devos	X	X	X	X	X	1
Frey	X	X	X	X	X	1
GVA Benzie	X	No	X	X	No	0
GVA Keweenaw	X	No	X	X	No	0
GVA Mackinac	X	No	X	X	No	0
GVA Oakland	X	No	X	X	No	0
GVA Tuscola	X	No	X	X	No	0
GVA Wexford	X	No	X	X	No	0
Hoobler	X	No	X	X	X	1
Hills	X	X	X	X	X	1
Johnson	X	No	X	X	X	1
Kistler	X	No	X	X	X	1
Kirkpatrick	X	X	X	X	X	1
Laker Village N	X	No	X	X	No	0
Laker Village S	X	No	X	X	No	0
Murray	X	X	X	X	X	1
North A	X	X	X	X	X	1
North B	X	X	X	X	X	1
North C	X	X	X	X	X	1
Niemeyer East	X	X	X	X	X	1
Niemeyer Honors	X	X	X	X	X	1
Niemeyer West	X	X	X	X	X	1
Ott	X	No	X	X	X	1
Pickard	X	No	X	X	X	1
Pew	X	No	X	X	X	1
Ravines	X	No	X	X	No	1
Robinson	X	No	X	X	X	1
South Apts. C	X	X	X	X	X	0
South Apts. D	X	X	X	X	X	1
South Apts. E	X	X	X	X	X	1
Seidman	X	X	X	X	X	1
Secchia Residence	X	X	X	X	X	2
Stafford	X	X	X	X	X	1
Swanson	X	X	X	X	X	1
VanSteeland	X	X	X	X	X	1
Weed	X	No	X	X	X	1
West A	X	X	X	X	X	1
West B	X	X	X	X	X	1
Winter Hall	X	X	X	X	X	2