

GVSU Housing Fire Safety Systems (2013)

Living Centers	Alarms Monitored at CUB	Sprinkler System	Smoke Detector	Fire Extinguisher	Evacuation Placards	Number of Annual Fire Drills
Copeland	X	No	X	X	X	3
Calder Residence	X	No	X	X	X	2
Devos	X	X	X	X	X	3
Frey	X	X	X	X	X	2
GVA Benzie	X	No	X	X	No	0
GVA Keweenau	X	No	X	X	No	0
GVA Mackinac	X	No	X	X	No	0
GVA Oakland	X	No	X	X	No	0
GVA Tuscola	X	No	X	X	No	0
GVA Wexford	X	No	X	X	No	0
Hoobler	X	No	X	X	X	3
Hills	X	X	X	X	X	2
Johnson	X	No	X	X	X	3
Kistler	X	No	X	X	X	3
Kirkpatrick	X	X	X	X	X	3
Laker Village N	X	No	X	X	No	0
Laker Village S	X	No	X	X	No	0
Murray	X	X	X	X	X	2
North A	X	X	X	X	X	2
North B	X	X	X	X	X	2
North C	X	X	X	X	X	2
Niemeyer East	X	X	X	X	X	2
Niemeyer Honors	X	X	X	X	X	2
Niemeyer West	X	X	X	X	X	2
Ott	X	No	X	X	X	4
Pickard	X	No	X	X	X	3
Pew	X	No	X	X	X	3
Ravines	X	No	X	X	No	0
Robinson	X	No	X	X	X	4
South Apts. C	X	X	X	X	X	2
South Apts. D	X	X	X	X	X	2
South Apts. E	X	X	X	X	X	2
Seidman	X	X	X	X	X	3
Secchia Residence	X	X	X	X	X	1
Stafford	X	X	X	X	X	3
Swanson	X	X	X	X	X	3
VanSteeland	X	X	X	X	X	2
Weed	X	No	X	X	X	4
West A	X	X	X	X	X	2
West B	X	X	X	X	X	2
Winter Hall	X	X	X	X	X	1